

Recording to ATNF V011/B1-B7 mounted as /data/xraid1

MMS frequencies 24975 MHz for LCP/RCP, 2nd LO 481.4 MHz

14:10:00 on point

14:23:00 changed from 1-4ch recording to 1,3ch only

14:31:00 ch1 and ch2 pol swapped

14:53:00 VSIC internal cable appeared to be loose, was tightend up

From:

<http://www.atnf.csiro.au/vlbi/dokuwiki/> - **ATNF VLBI Wiki**

Permanent link:

<http://www.atnf.csiro.au/vlbi/dokuwiki/doku.php/lbaops/lbajul2011/vc151tilog>

Last update: **2015/12/18 16:38**

