

Recording to Flexbuf, disk0

Recording RCP, LCP (confirmed with fringecheck)

Agilent 12.2 GHz

SML01/02 810 MHz or 468/810 MHz (ICRF)

Coherence seen with tone of 664.7 MHz

03:59 UT - eRemote Control errors that "Video converter freq. must be between 100 and 500 MHz". The power levels on some of the VCs are ~3. JMc not contactable (vk). Error not significant as mark4 rack not in use for this experiment.

From:

<https://www.atnf.csiro.au/vlbi/dokuwiki/> - **ATNF VLBI Wiki**

Permanent link:

<https://www.atnf.csiro.au/vlbi/dokuwiki/doku.php/lbaops/lbajul2015/v255yholog>

Last update: **2015/12/18 16:38**

