

Recording to Flexbuf, disk0

Recording RCP, LCP (confirmed with fringecheck)

Agilent 14 GHz

SML01/02 777 MHz

Coherence seen with tone of 841.4 MHz

DAS profile 64MHZ_N.PRO

DAS restarted at 0755 after program locked up.

Recording restarted at 1052 to deal with incorrect initial recording time.

From:

<https://www.atnf.csiro.au/vlbi/dokuwiki/> - **ATNF VLBI Wiki**

Permanent link:

<https://www.atnf.csiro.au/vlbi/dokuwiki/doku.php/lbaops/lbajul2015/v486fholog>

Last update: **2015/12/18 16:38**

