

Recording to ATNF-V011/B1-B7 mounted as /data/xraid1

DAS profile 64MHz_f.pro, 2nd IF 485 MHz

07:05:20 on point

07:29:30 antenna didn't start slewing to the next source due to antenna control problem

07:31:50 Started slewing

13:29:30 antenna didn't start slewing to the next source due to antenna control problem

Switched to APCcontrol program to send predicts from PC-field system

13:30:38 Started slewing

14:59:30 End of schedule

From:

<https://www.atnf.csiro.au/vlbi/dokuwiki/> - **ATNF VLBI Wiki**

Permanent link:

<https://www.atnf.csiro.au/vlbi/dokuwiki/doku.php/lbaops/lbajun2011/vt14ntilog>



Last update: **2015/12/18 16:38**