

Mopra recording to local xraid ATNF V015A. But a disk change would be necessary for the last 4.5hrs, which happened.

Atten on freq 2A at 0,0 and DAS reporting low levels at around 17:11 UT. But stats seemed ok. So DAS monitoring stopped to avoid alarms. Only for the one scan (10mins). This happened a few more times

~06:10 UTC realised focus had not been adjusted.

From:

<http://www.atnf.csiro.au/vlbi/dokuwiki/> - **ATNF VLBI Wiki**

Permanent link:

<http://www.atnf.csiro.au/vlbi/dokuwiki/doku.php/lbaops/lbajun2013/v252akmplog>

Last update: **2015/12/18 16:38**

