

Recording disk BI\_1 ATNF V006A

Frequency modes did not change as expected. Therefore, delay cal was observed only at single freq. ICRF run stayed at single freq. until ~ 02:48 UT at which time I changed it manually.

Ceduna's status reads SLEWING continuously on monit2. This appears to have begun sometime around 21:33 UT.

From:

<https://www.atnf.csiro.au/vlbi/dokuwiki/> - **ATNF VLBI Wiki**

Permanent link:

<https://www.atnf.csiro.au/vlbi/dokuwiki/doku.php/lbaops/lbajun2013/v255scdlog>



Last update: **2015/12/18 16:38**