

**N.B.: No fringes found and later discovered 100 MHz LO reference not connected! Data not useful.**

ASKAP drive problems... potentially... Az drives had servo and brakes red but telescope appeared to perhaps track.

Restarted at 16:37UT. May have lost some time before that.

From:

<https://www.atnf.csiro.au/vlbi/dokuwiki/> - **ATNF VLBI Wiki**

Permanent link:

<https://www.atnf.csiro.au/vlbi/dokuwiki/doku.php/lbaops/lbajun2013/vx017baklog>



Last update: **2015/12/18 16:38**