

Agilent : 13.040 GHz
SML01/02 : 637/637 MHz
Tone : 841.4 MHz
DAS Profile : VSOP.PRO
Disk : CURT V004B
Observers : Chris J, Yurii

Problems with DAS profile prior to 11:48 UT. For most of the time prior to this IF#1 was LSB rather than USB, although for some of the time we had VSOP_HO.PRO running and it has both IF#1 and IF#2 inverted. Also, frequent switching on of strong tones prior to 12:00 UT

Online and recording as of around 13:00 UT.

From:
<http://www.atnf.csiro.au/vlbi/dokuwiki/> - **ATNF VLBI Wiki**

Permanent link:
<http://www.atnf.csiro.au/vlbi/dokuwiki/doku.php/lbaops/lbajun2014/v495acdlog>

Last update: **2015/12/18 16:38**

