

## Reference Antenna W104

Most data up UT 00:40 will be de-correlated due to scheduling error.

UT 00:40 Noticed that auto-phase calibration command was being issued on 0857-473, which has structure on ATCA baselines. Found software bug in schedule file that meant this command was being issued to many sources, regardless of their suitability as a phase calibrator. This was corrected by Chris Philips, data from UT 00:55 should be fine.

~10:30 UTC block 27 failed. Reprogrammed - lost about 5min

~20:28 UT LBA Recmon alarm that ATCA not recording. Restart recording.

From:

<https://www.atnf.csiro.au/vlbi/dokuwiki/> - **ATNF VLBI Wiki**

Permanent link:

<https://www.atnf.csiro.au/vlbi/dokuwiki/doku.php/lbaops/lbajun2016/v493catlog?rev=1467232352>

Last update: **2016/06/30 06:32**

