

After a pcal, some RFI in IF1 made the phases wrong. Plus, since the noise diode was off, the polarisations would have been awful after the pcal.

Stopped main schedule to fix this issue at 00:15:15, was back on main schedule at 00:20:20

From:

<http://www.atnf.csiro.au/vlbi/dokuwiki/> - **ATNF VLBI Wiki**

Permanent link:

<http://www.atnf.csiro.au/vlbi/dokuwiki/doku.php/lbaops/lbajun2016/v537batlog>

Last update: **2016/06/26 10:23**

