

Fringes found through LBA DAS recording of lower two IFs, but not through DBBC/mark 5.
Some issues with the Mark 5 corrected at approximately 23 UT (see PCFS logs for details)
Discovered that Ceduna was duplicate recording RCP, rather than RCP/LCP prior to 23 UT (see PCFS log for details)

From:

<https://www.atnf.csiro.au/people/atzioumi/vlbi/dokuwiki/> - **ATNF VLBI Wiki**

Permanent link:

<https://www.atnf.csiro.au/people/atzioumi/vlbi/dokuwiki/doku.php/lbaops/lbajun2017/v559acdlog> 

Last update: **2017/06/15 09:14**