

07:36 UT Second LO freq. for the second channel has been corrected from 430MHz to 462 MHz.

From:

<https://www.atnf.csiro.au/vlbi/dokuwiki/> - **ATNF VLBI Wiki**

Permanent link:

<https://www.atnf.csiro.au/vlbi/dokuwiki/doku.php/lbaops/lbamar2007/v190htilog>

Last update: **2015/12/18 16:38**

