

Adjustment of the 5MHz maser reference current by Brett Preisig and Shaun Amy (to ensure the 5MHz would not drift out of lock) during slews between 21:37 and 21:49. During this period, we do not believe that the 5MHz reference was affected (i.e. it remained in lock at all times).

From:  
<https://www.atnf.csiro.au/vlbi/dokuwiki/> - **ATNF VLBI Wiki**

Permanent link:  
<https://www.atnf.csiro.au/vlbi/dokuwiki/doku.php/lbaops/lbamar2010/v271epalog?rev=1268334018>

Last update: **2015/12/18 16:38**

