

Recording Mk5b.

Parallel recording on pkvsi2:/xraid0 disk ATNF V013B.

Adjustment of the 5MHz maser reference current by Brett Preisig and Shaun Amy (to ensure the 5MHz would not drift out of lock) during slews between 21:37 and 21:49. During this period, we do not believe that the 5MHz reference was affected (i.e. it remained in lock at all times).

From:

<https://www.atnf.csiro.au/vlbi/dokuwiki/> - **ATNF VLBI Wiki**

Permanent link:

<https://www.atnf.csiro.au/vlbi/dokuwiki/doku.php/lbaops/lbamar2010/v271epalog?rev=1268351334>

Last update: **2015/12/18 16:38**

