

Ak records 64 MHz, centred on 1674 MHz.

Timed vlbi\_drv start at 16:16:40UT. Seemed to have started ok.

Timed recording started at 16:15UT. Seemed ok.

px14 stopped at 20:17:40UT for a restart. Needed to reset the module! Back on 20:29:13UT.

From:

<https://www.atnf.csiro.au/vlbi/dokuwiki/> - **ATNF VLBI Wiki**

Permanent link:

<https://www.atnf.csiro.au/vlbi/dokuwiki/doku.php/lbaops/lbamar2012/v452baklog>



Last update: **2015/12/18 16:38**