

Started recording on time, but the recorder took a while to start up, so probably missed the first minute.

Once I got Ak going, went off to do Pk and At, but upon return found the drive software had crashed here. Restarted everything, but the servo loop for el refused to clear. A "drive_off" then "drive_on" and a restart of vlbi_drv fixed this problem.

Recording to xraid_1.

Drive controls probably dead at 07:109 UTC - restarted then

From:

<http://www.atnf.csiro.au/vlbi/dokuwiki/> - **ATNF VLBI Wiki**

Permanent link:

<http://www.atnf.csiro.au/vlbi/dokuwiki/doku.php/lbaops/lbamar2013/v252ajaklog>

Last update: **2015/12/18 16:38**

