

DAS profile 16_UL_F.PRO

Agilent 17.4 GHz

SML01/02 416 MHz

(weak) coherence seen with tone of 889.24 MHz

Recording RCP/LCP

Recording to CURT V005B

drive PC error 1430-1445

From:

<https://www.atnf.csiro.au/people/atzioumi/vlbi/dokuwiki/> - **ATNF VLBI Wiki**

Permanent link:

<https://www.atnf.csiro.au/people/atzioumi/vlbi/dokuwiki/doku.php/lbaops/lbamar2014/ga030dcdlog>

Last update: **2015/12/18 16:38**

