

Some issues with one of the Parkes polarizations. During times when Parkes is not participating the receiver was switched off to “rest” the amplifiers and help

Times when the receiver was rested :

10:15 - 10:40 UT

14:00 - 14:45 UT

From:

<https://www.atnf.csiro.au/vlbi/dokuwiki/> - **ATNF VLBI Wiki**

Permanent link:

<https://www.atnf.csiro.au/vlbi/dokuwiki/doku.php/lbaops/lbamar2015/v255xpalog?rev=1427466550>

Last update: **2015/12/18 16:38**

