

Problem with DAS clocks - many PPS errors and recorder issues. Fixed with a DAS reconf in the last 10minutes

From:

<http://www.atnf.csiro.au/vlbi/dokuwiki/> - **ATNF VLBI Wiki**

Permanent link:

<http://www.atnf.csiro.au/vlbi/dokuwiki/doku.php/lbaops/lbamar2016/v537atilog>

Last update: **2016/03/04 20:58**

