

The antenna was windstowed for much of the experiment and the RF setup was not able to be properly tested, we think that it is likely that Hobart was not working properly.

We know that we have one bad polarisation channel on the 4.8 GHz receiver, but were not able to do test scans or measure system temperature for this experiment because of a range of technical issues. Data was recorded, but we do not recommend spending very long searching for Fringes to Hobart.

From:

<https://www.atnf.csiro.au/vlbi/dokuwiki/> - **ATNF VLBI Wiki**

Permanent link:

<https://www.atnf.csiro.au/vlbi/dokuwiki/doku.php/lbaops/lbamar2018/gg084aholog>

Last update: **2018/03/14 07:38**

