

Record to internal disks

## OBSERVING LOG

---

Problems with vlobs changing frequencies. Period ~015 to ~12:05UT may be at wrong frequency.

Some attenuator setting problems 0320-0330UT. Tsys values 0. Data may be corrupted.

DAS1 monitoring crashed 03:35UT. Did not get restarted. Data should be ok as levels were maintained within range.

From:

<https://www.atnf.csiro.au/vlbi/dokuwiki/> - **ATNF VLBI Wiki**

Permanent link:

<https://www.atnf.csiro.au/vlbi/dokuwiki/doku.php/lbaops/lbamay2006/v184amplog>

Last update: **2015/12/18 16:38**

