

Ho data probably bad, due to a problem with the 6.7 GHz receiver. I was resetting things for the first two hours of the schedule, recording is uninterrupted from around 05:40.

Hb was put on schedule from 05:57 as backup. Telescope was not in original vex file (I think), setup of the data is the usual two streams (c=X-pol, d=Y-pol) with 32 MHz USB channels (same as Ke).

Gabor

From:

<https://www.atnf.csiro.au/vlbi/dokuwiki/> - **ATNF VLBI Wiki**

Permanent link:

<https://www.atnf.csiro.au/vlbi/dokuwiki/doku.php/lbaops/lbamay2021/v255alnolog>

Last update: **2021/05/31 15:21**

