

Started recording to PKS+0017.

Problems with Mark5B recording. (System went into unusable state, giving timing problems, reset did not help, ended up requiring complete power down to fix)

Also JER later discovered wrong synthesiser connected in focus cabin, so Parkes has no valid data for this experiment.

From:

<https://www.atnf.csiro.au/vlbi/dokuwiki/> - **ATNF VLBI Wiki**

Permanent link:

<https://www.atnf.csiro.au/vlbi/dokuwiki/doku.php/lbaops/lbanov2011/v271jpalog>

Last update: **2015/12/18 16:38**

