

Data recorded to CURT V003B

Agilent at 4.1 GHz

SML01/Agilent01 set to 602 MHz

SMY01 set to 819.5 MHz

Recording RCP/LCP

Polarization purity poor, cause unknown.

on/offsource flag files generated automatically from PCFS logs for this session for Hobart likely to be of little use.

From:

<https://www.atnf.csiro.au/vlbi/dokuwiki/> - **ATNF VLBI Wiki**

Permanent link:

<https://www.atnf.csiro.au/vlbi/dokuwiki/doku.php/lbaops/lbanov2012/v389cholog>

Last update: **2015/12/18 16:38**

