

Agilent 17.4 GHz

SML01/02 = 336 MHz

DAS profile VSOP.PRO with the "SWAP SIDEBANDS" bit set manually. There is currently a problem with our DAS installation where it is not parsing the profiles correctly (or not controlling the filters correctly)

Coherence seen with tone of 892.2 in bandsplitter port

Recording RCP/LCP

Recording to CURT V004B

Weather conditions are cold and clear. Mild winds.

From:

<https://www.atnf.csiro.au/vlbi/dokuwiki/> - **ATNF VLBI Wiki**

Permanent link:

<https://www.atnf.csiro.au/vlbi/dokuwiki/doku.php/lbaops/lbanov2013/v252ancdlog>



Last update: **2015/12/18 16:38**