

Observer John Dickey

Recording to CURT 007A

recorder started d324h11m18s00

weather overcast, fine

SML01 810MHz, SML02 810MHz, Agilent 12.2 GHz

DAS VSOP.pro

Fringe check good.

formatter-GPS counter was malfunctioning throughout this experiment and recorded a value of 0.99s. The correct maser-GPS offset is ~4.8 microseconds

From:

<http://www.atnf.csiro.au/vlbi/dokuwiki/> - **ATNF VLBI Wiki**

Permanent link:

<http://www.atnf.csiro.au/vlbi/dokuwiki/doku.php/lbaops/lbanov2013/v316eholog>

Last update: **2015/12/18 16:38**

