

Recording RCP/LCP

Agilent 4.1 GHz

SML 602 MHz

DAS: VSOP_HO.PRO

Coherence seen with tone of 819.5 MHz

Recording to ATNF V016B

formatter-GPS counter was malfunctioning throughout this experiment and recorded a value of 0.99s. The correct maser-GPS offset is ~4.8 microseconds

From:

<https://www.atnf.csiro.au/vlbi/dokuwiki/> - **ATNF VLBI Wiki**

Permanent link:

<https://www.atnf.csiro.au/vlbi/dokuwiki/doku.php/lbaops/lbanov2013/v389dholog>



Last update: **2015/12/18 16:38**