

Pols are swapped

DAS2 is not communicating. Have swapped frequencies between 6.7 and 6.0 GHz.

DAS2 had no mains. Powered up and connected ok, before Pks was on the sources. No data lost.

Drives glitched. 00:12 UT to 00:15UT. System picked up ok.

From:

<https://www.atnf.csiro.au/vlbi/dokuwiki/> - **ATNF VLBI Wiki**

Permanent link:

<https://www.atnf.csiro.au/vlbi/dokuwiki/doku.php/lbaops/lbanov2013/v452cpalog>



Last update: **2015/12/18 16:38**