

Recorded to DVP Mark5c JPL-0060/1024/4000

er051_43.CFG_if01 :: "? 1325 DSS-AUX1 unknown" _if02 :: "S 1380 DSS-43 N/A" _vc01 :: "_if02 290"
_vc02 :: "_if01 290" _vc03 :: "_if02 322" _vc04 :: "_if01 322" _vc05 :: "_if02 354" _vc06 :: "_if01 354"
_vc07 :: "_if02 386" _vc08 :: "_if01 386"

16:32:35 On source 0503-295

Pointing predicts are not updated until 19:01:28 due to an operational issue

19:01:46 On source 0503-295

19:05:08 On source ESO422

20:48:15 Stop antenna

20:48:21 Stow antenna

From:

<https://www.atnf.csiro.au/vlbi/dokuwiki/> - **ATNF VLBI Wiki**

Permanent link:

<https://www.atnf.csiro.au/vlbi/dokuwiki/doku.php/lbaops/lbanov2019/er051tilog?rev=1572902193>

Last update: **2019/11/05 08:16**

