

The C-band VLBI scans between 0840 and 0900 have been changed to K-band, as we cannot support rapid receiver changes.

Recording using the DBBC/Mark5C.

Fringes found, although very weak. Problem appears to be a serious pointing offset (~1.8' in Azimuth), unable to be easily corrected.

Main experiment uses a higher IF power target than in fringe testing.

Pols correct.

Recording to HOB+1009/16000/1024

Good weather, system temperature appears very good.

From:

<https://www.atnf.csiro.au/people/atzioumi/vlbi/dokuwiki/> - **ATNF VLBI Wiki**

Permanent link:

<https://www.atnf.csiro.au/people/atzioumi/vlbi/dokuwiki/doku.php/lbaops/lbaoct2016/gg081bcdlog> 

Last update: **2016/10/18 18:40**