

The C-band scans between 0840 and 0900 have been changed to K-band instead. We cannot support rapid receiver changes during an experiment.

Using DBBC/Mark5B

Pls correct

Fringes found.

Recording to HOB+0093

Poor weather - several fronts of rain have moved through.

From:

<http://www.atnf.csiro.au/vlbi/dokuwiki/> - **ATNF VLBI Wiki**

Permanent link:

<http://www.atnf.csiro.au/vlbi/dokuwiki/doku.php/lbaops/lbaoct2016/gg081bholog>

Last update: **2016/10/18 18:41**

