

DSS-43 (Tid70m) observed this at L-band LCP only

das profile: 16MHz_ul_f.pro

2ndLO 448 MHz

Note added on DOY 298: It appears the frequency set up for this experiment might have been wrong, recording 1613 MHz +/- 16MHz instead of 1668 MHz +/- 16 MHz. We will send the data anyway just in case.

From:

<https://www.atnf.csiro.au/vlbi/dokuwiki/> - **ATNF VLBI Wiki**

Permanent link:

<https://www.atnf.csiro.au/vlbi/dokuwiki/doku.php/lbaops/lbaoct2016/rk16bhtilog>

Last update: **2016/10/25 14:34**

