

Fringes detected in all channels to parkes

proc file edited to use alt inputs & correct patching.

define ifd01 14262193911x ifd=17,9,alt,alt if3=5,in,2,1,,,on

Using sam26m Tsys rather than mark4 rack due to uncertainty in noise diode calibration.

Stopped due to wind at 8:45 UT and has not resumed.

From:

<https://www.atnf.csiro.au/vlbi/dokuwiki/> - **ATNF VLBI Wiki**

Permanent link:

<https://www.atnf.csiro.au/vlbi/dokuwiki/doku.php/lbaops/lbasep2014/v527bholog>



Last update: **2015/12/18 16:38**