

Recording DAS1 to mpvsi1, disk ATNF V014B. DAS1 is using profile 64MHz_n.pro.

Recording DAS2 to mpvsi2, disk CURT V002B. DAS2 is using profile 64MHz_f.pro.

Fringes were obtained using data from both DAS during checks before the experiment, but those same checks indicate that there is a problem with one channel of DAS2. The primary symptom of this problem is a very unstable bandpass; unfortunately there was nothing we could do about this for this experiment.

From:

<https://www.atnf.csiro.au/people/Tasso.Tzioumis/vlbi/dokuwiki/> - **ATNF VLBI Wiki**

Permanent link:

<https://www.atnf.csiro.au/people/Tasso.Tzioumis/vlbi/dokuwiki/doku.php/lbaops/lbasep2015/bk193amplog>

Last update: **2015/12/18 16:38**

