

Recording to CURT V007A

No First LO.

Second LO set to 436 MHz.

DAS profile 64MHz\_n.pro

UT ~02:26 Wind stow.

UT ~02:32 Back on schedule.

UT ~03:11 Wind stow.

UT ~03:18 Back on schedule.

UT ~04:30 Rack power outage. Recorder offline.

UT ~04:50 Recording again.

UT ~05:10 Wind stow.

Back on source minutes later, but stowed again UT 05:20. Gusty conditions making it difficult to stay on source.

UT 06:40 Installed VLBI wind limits disk in drive PC. Might help reduce the number of stows.

UT ~07:11 Wind stow.

UT ~07:16 Back on schedule.

UT ~07:18 Wind stow.

UT ~07:24 Back on schedule.

From:

<http://www.atnf.csiro.au/vlbi/dokuwiki/> - **ATNF VLBI Wiki**

Permanent link:

<http://www.atnf.csiro.au/vlbi/dokuwiki/doku.php/lbaops/lbadec2009/v310acdlog>

Last update: **2015/12/18 16:38**

