

DSS-43 L-Band LCP

2nd LO 503 MHz

Recording to ATNF_V011B1-7 mounted as /data/xraid0

DSS-43 has problem with L-Band LNA switch (S90)

09:59:31 on source

10:02:00 fringe to ATCA/Parkes/Mopra confirmed

10:08:23 stop observing for troubleshooting

13:00:00 End of schedule

From:

<http://www.atnf.csiro.au/vlbi/dokuwiki/> - **ATNF VLBI Wiki**

Permanent link:

<http://www.atnf.csiro.au/vlbi/dokuwiki/doku.php/lbaops/lbafeb2014/v506btilog>

Last update: **2015/12/18 16:38**

