

schedule=v289dho,#18

evlbi.

Lband 1720 sky agilent 4.1

smy 532

coherence 5th harmonic of 341.8 = 1709 MHz

DAS profile VSOP_HO.pro

This expt should be RCP,LCP but 1 linear LNA is broken. So Linear 1 is fed to both signal paths.

Simon performed a calibration scan. sytemps in log need scaling.

Brett

From:

<http://www.atnf.csiro.au/vlbi/dokuwiki/> - **ATNF VLBI Wiki**

Permanent link:

<http://www.atnf.csiro.au/vlbi/dokuwiki/doku.php/lbaops/lbajul2009/v289dolog>

Last update: **2015/12/18 16:38**

