

Ref CA01 on W104.

Tied 1245 1245. CA03 off-line. Could not calibrate cross-pols.

Late on schedule. On-source and all ok at 04:44 UT.

~06:04 UT. Delay glitch. Both 12aa and 14bb amplitudes very high!!

06:33 UT Tied only 15 15 !! Only way to keep it working...

From:

<http://www.atnf.csiro.au/vlbi/dokuwiki/> - **ATNF VLBI Wiki**

Permanent link:

<http://www.atnf.csiro.au/vlbi/dokuwiki/doku.php/lbaops/lbajul2009/v289gatlog>

Last update: **2015/12/18 16:38**

