

Ref CA01 on W104. Config H75. Tied 12345.

~05:40-06:05 UT.. Array comms problems. Antennas intermittently idle!!

Problems again at around 06:40UT

06:44:15UT. ATCA changed to linear polarisations in catie.

From:

<http://www.atnf.csiro.au/vlbi/dokuwiki/> - **ATNF VLBI Wiki**

Permanent link:

<http://www.atnf.csiro.au/vlbi/dokuwiki/doku.php/lbaops/lbajul2009/v289jatlog>

Last update: **2015/12/18 16:38**

