

Observers : Vasaant (first half) and Simon (second half)

Agilent : 11.1 GHz

SML01/02 : 468/810 MHz (ICRF) & 810/810 MHz (maser)

Das profile : VSOP.PRO

Disk : ATNF V012A

Problem with the drive PC - antenna ended up in limit and Bev had to go out and drive it out.

Antenna windstowed at 07:32:03 and no good data (it appears) until,

Antenna back onsource at 10:57:14 (although with maser frequency setup when should have been ICRF) and at correct frequency at 11:06:33

From:

<http://www.atnf.csiro.au/vlbi/dokuwiki/> - **ATNF VLBI Wiki**

Permanent link:

<http://www.atnf.csiro.au/vlbi/dokuwiki/doku.php/lbaops/lbamar2014/v255vcdlog>

Last update: **2015/12/18 16:38**

