

From about 4:40/247 UT/DOY until 4:56/247 we lost the external reference phase lock on the 2nd LO. The oscillator was accidentally turned off and the LO signal was also lost for a minute or two, before the unit was turned back on. Observer, Warren. The DAS aborted at UT 10:08. I restarted with vsop.pro. Shortly after I checked coherence and did not find it. I reprogrammed the das using profile vsop_ho.pro. This time I got coherence. Finished at 10:30 UT. jd

From:

<http://www.atnf.csiro.au/vlbi/dokuwiki/> - **ATNF VLBI Wiki**

Permanent link:

<http://www.atnf.csiro.au/vlbi/dokuwiki/doku.php/lbaops/lbasep2009/v255folog?rev=1252061222>

Last update: **2015/12/18 16:38**

