

Real-time fringe check revealed delay jump on all AT baselines. Based on times when the fringe finders were observed, the issue occurred sometimes between 03:31 UT and 06:58 UT (i.e. during the first 1/3 of the science block).

RFI may have affected auto-phasing for one of the supplementary fringe finders observed before the science block (J1337-1257?), but phasing was alright for the first 1740-517 at 03:32 UT. The array configuration is H214.

CI1F1 PLL unlocked for ca04 in monica, nothing obvious in vis, probably doesn't matter.

From:

<http://www.atnf.csiro.au/vlbi/dokuwiki/> - **ATNF VLBI Wiki**

Permanent link:

<http://www.atnf.csiro.au/vlbi/dokuwiki/doku.php/lbaops/lbasep2018/v560batlog>

Last update: **2018/09/11 12:41**

