

DAS setup issues at start. DASPRO wrong!!

Changed to correct profile av16_2_n.pro about 16:00 UT. Fringes ok after that.

About 23:37 UT TPS stowed dish. Recoverd ok by just unstow.

Dish stow/unstow to reset TPS. Lost 10 mins 23:48-23:58 UT.

16:26UT - 16:38 UT. Stow/unstow to clear DCP alarm.

From:

<https://www.atnf.csiro.au/vlbi/dokuwiki/> - **ATNF VLBI Wiki**

Permanent link:

<https://www.atnf.csiro.au/vlbi/dokuwiki/doku.php/lbaops/lbaaug2013/v252alpalog>



Last update: **2015/12/18 16:38**