

- Recording data at 22:29 to ATNF V016B
- Using DAS profile 64MHZ\_N.PRO
- Agilent at 10.5 GHz
- Second LO 668 MHz
- Coherence tone (961 MHz) just turned off
- Coherence occurs at  $4816-16+5=4805$  MHz, rather than  $4816-32+5$  as expected. Due to the DAS always giving out 16 MHz outputs.
- Recording at 64 MHz per channel, channels 1,2 via cDiso. BG3 cable installed.
- Stats are ok and BIGBUF ok.
- Recording RCP, LCP
- Systems failed due to formatting errors in the copy/paste

From:

<http://www.atnf.csiro.au/vlbi/dokuwiki/> - **ATNF VLBI Wiki**

Permanent link:

<http://www.atnf.csiro.au/vlbi/dokuwiki/doku.php/lbaops/lbadec2009/vt10iholog>

Last update: **2015/12/18 16:38**

