2020/02/28 16:42 1/1

341/16:01 - 18:11, 19:21 - 22:11 and 341/23:31 - 342/07:31 recorded to pack HART+523/32000/1024 (797.8 GiB).

Scans no0039-no0040 lost due to DEC encoder readout jumps causing an antenna controller failure. Time-range gaps above due to recording rk25al and rk25am as pre-arranged. No other known problems.

DAS profiles: N/A (Mark 5/DBBC) Clock offset (station-GPS) = +8.92us.

Weather: Partly cloudy throughout the experiment.

Observer(s): Jonathan Quick.

https://www.atnf.csiro.au/vlbi/dokuwiki/ - ATNF VLBI Wiki

Permanent link:



