

All data after ~1640 lost due to the second disk being released for reuse prematurely.

Comments from the log file:

2014.035.16:40:12.80; "recorder stopped & restarted to avoid running out of disk space

2014.035.21:51:45.15; "LCP n receiver has developed a fault and is essentially unusable

From:

<http://www.atnf.csiro.au/vlbi/dokuwiki/> - **ATNF VLBI Wiki**

Permanent link:

<http://www.atnf.csiro.au/vlbi/dokuwiki/doku.php/lbaops/lbafeb2014/g032cholog>

Last update: **2015/12/18 16:38**

