

No fringes during testing, likely caused by large offset in mark5B header time (2s integer offset?)

From:

<https://www.atnf.csiro.au/vlbi/dokuwiki/> - **ATNF VLBI Wiki**

Permanent link:

<https://www.atnf.csiro.au/vlbi/dokuwiki/doku.php/lbaops/lbajan2015/rk08occdlog>

Last update: **2015/12/18 16:38**

