

Note that attenuators are set to values that do not agree with wiki notes:

mm atten: 12 Coarse atten: 2 3

However the Tsys and DAS levels look fine, so these are perhaps the new good values.

From:

<https://www.atnf.csiro.au/people/atzioumi/vlbi/dokuwiki/> - **ATNF VLBI Wiki**

Permanent link:

<https://www.atnf.csiro.au/people/atzioumi/vlbi/dokuwiki/doku.php/lbaops/lbajan2018/gg083cmplog>

Last update: **2018/02/01 17:54**

