

Recording to SWIN-V013-B1-7

08:45 on point, the sky was with patchy clouds

09:44 Fringes to Tid appeared to be too weak

10:20 Stopped antenna to fix sub-reflector

10:30 Resumed schedule from 1057-797 scan, yielding good fringes

Data before this time suffered low gain as sub-reflector appeared to be not at right angle although the antenna control system had been indicating as at the correct position.

13:50 the weather is clear

15:00-15:10 scan for 2027-308 has been skipped because of too long slew to reach

16:00-16:10 scan for 0055-328 has been skipped because of too long slew to reach

16:20-16:30 scan for 2027-308 has been skipped because of too long slew to reach

17:40-17:50 scan for 0055-328 has been skipped because of too long slew to reach

17:40-17:50 scan for 0055-328 has been skipped because of too long slew to reach

18:10-18:20 scan for 0055-328 was missed because of too long slew to reach

18:30 schedule terminated

Note added on 2010 August 7 - tsys files and flag table have been uploaded to ftp area

From:

<https://www.atnf.csiro.au/vlbi/dokuwiki/> - **ATNF VLBI Wiki**

Permanent link:

<https://www.atnf.csiro.au/vlbi/dokuwiki/doku.php/lbaops/lbajul2009/v252mtilog>

Last update: **2015/12/18 16:38**

