

- recorded to ATNF V005 B1 - B7
- removed BG3 cable - now straight through

Recording to V005B

Ceduna not recording between 2218-2234 . Recorder stopped to fix scheduled start error, but not restarted correctly.

Tone @ 8456.0005 MHz between 2318-2329

From:

<https://www.atnf.csiro.au/vlbi/dokuwiki/> - **ATNF VLBI Wiki**

Permanent link:

<https://www.atnf.csiro.au/vlbi/dokuwiki/doku.php/lbaops/lbajul2009/v271ccdlog?rev=1246772007>

Last update: **2015/12/18 16:38**

